



Questions and Answers: For Use in the Instruction of Torpedo Companies and Detachments (Classic Reprint)

By Unknown Author

Forgotten Books, United States, 2015. Paperback. Book Condition: New. 229 x 152 mm. Language: English . Brand New Book ***** Print on Demand *****.Excerpt from Questions and Answers: For Use in the Instruction of Torpedo Companies and Detachments Brass jointers are used when authorized. Before placing the joint in water, the turk s heads must be clamped in a distribution box or junction box. 4. Name all the parts of an assembled mine. Mine case, mine cap, compound plug, complete - including plug proper, lower tube, fuze can cap, fuze can, mine transformer, ball seat, circuit-closer case, distance ring, springs, steel ball, 2 brass washers, 2 rubber packings, 1 brass follower, 1 steel follower, 3 lead washers, and set screws; loading wire, C wire, priming charge, 2 fuzes, 100 pounds of explosive, and ruberine. 5. Explain how to prepare a compound plug. The transformer to be used is first tested for a good circuit between the red wires, a poor circuit between the black wires, no circuit between the red and black wires, and no circuit between either wire and case. The upper black resistance terminal is cut to 11/2 inches in length, the end bared, and then clamped in...



READ ONLINE
[8.33 MB]

Reviews

The publication is easy in read through safer to comprehend. It is actually loaded with wisdom and knowledge Its been printed in an extremely simple way and is particularly simply right after i finished reading through this pdf where actually modified me, affect the way i believe.

-- **Ms. Clementina Cole V**

This is the very best publication i have got read until now. It is definitely simplified but shocks within the fifty percent of the pdf. You may like how the article writer create this pdf.

-- **Rosario Durgan**